## **SECTION 3**

## WATER PUMP RING MOUNT RADIATOR



Rotax aircraft engines are manufactured and supported by Rotax GmbH of Austria. Read and understand the <u>Rotax manuals</u> completely before starting with the engine installation, as they contain important engine installation, operation and maintenance information. Follow all of the <u>important safety</u> <u>information</u> provided in the Rotax manuals regarding the installation, operation and maintenance of the Rotax engine. <u>Read and understand the Rotax Operator's Manual before starting the engine</u>.

Make sure that your engine is registered with Rotax or an authorized distributor so that the factory warranty is in effect. In the United States, the Rotax distributor is Kodiak Research: http://www.kodiakbs.com Contact a Rotax distribution or service partner if you do not understand the instructions or if you have any additional questions. Maintain copies the manuals with the aircraft in case of sale. Obtain current versions of the manuals from the official Rotax website, as well as current service and maintenance information: www.rotax-aircraft-engines.com


If a discrepancy arises between the information provided by Rotax and the following pages, the Rotax manuals and/or service information and instructions take precedence. Zenith Aircraft Company does not manufacture or directly support engines.

<u>Alternative engines</u> will affect performance, specifications and flight characteristics of the aircraft. Also, the weight and balance of the aircraft may be adversely affected by alternative engines, and the original fuel system may not be adequate or suitable for some engines. Most alternative engines will require a custom engine mount and engine cowl.

Revision 1.0 (1/8/2007) © 2007 Zenith Aircraft Co 912S RING MOUNT Section 3 - Page 1 of 13



Reinstall the water pump.





## Threadlocker Medium strength 242.




Ref. Rotax CD (supplied with engine).



Section 13.3.10 Water pump housing-assembly (page 59).

Ref: Rotax Manual, Heavy Maintenance Manual II, section 13.3.10 page 59 for water pump reinstallation.

STOL<br/>CH 701Zenith Aircraft Company<br/>www.zenithair.comRevision 1.0 (1/8/2007)<br/>© 2007 Zenith Aircraft Co912S RING MOUNT<br/>Section 3 - Page 2 of 13





Reinstall the hoses and clamps: Detail of left side.

Left side, hoses through bottom Ring Mount Attachment.





Reinstall the hoses and clamps: Detail of right side.

Right Lower Ring Mount Attachment.

STOL CH 701

Revision 1.0 (1/8/2007) © 2007 Zenith Aircraft Co 912S RING MOUNT Section 3 - Page 3 of 13





P/N: 945-753 Lock washer

upper bolts: short = left, long = right



Top left Ring Mount Attachment

Note: Allen socket with 6" extension.



short = top left 10M x 35

**P/N:** 941-481-35 **P/N:** lock washer 945-753

Add threadlocker on threads.

STOL CH 701

912S RING MOUNT Section 3 - Page 4 of 13



Top Right Ring Mount Attachment.



long = top right 10M x 110mm.

**P/N:** 941-481-110 **P/N:** lock washer 945-753

Add threadlocker on threads.





Bottom right Ring Mount Attachment

STOL CH 701

Revision 1.0 (1/8/2007) © 2007 Zenith Aircraft Co 912S RING MOUNT Section 3 - Page 5 of 13





THRUST WASHERS (Flat thin washers) **P/N:** 927-952.

If there is a gap between the bottom ring mount fitting to the engine, slide a flat washer between the engine block and the mount.





With a screw driver line up the washer.

Look in the hole to check the washer is line up with the tapped hole.

STOL CH 701

Revision 1.0 (1/8/2007) © 2007 Zenith Aircraft Co 912S RING MOUNT Section 3 - Page 6 of 13





Radiator mounting brackets 1L + 1R required.

Right bracket **P/N:** R-CB.





Washer between the aluminum bracket and the lock washer.

Flat washers 4 required.

Left bracket **P/N:** L-CB.

STOL CH 701 Revision 1.0 (1/8/2007) © 2007 Zenith Aircraft Co

912S RING MOUNT Section 3 - Page 7 of 13



Rear right bolt. 15.5mm spacer fits inside engine mount recessed hole.



**P/N:** Bolt 941-481-55. **P/N:** Lock washer 945-753. **P/N:** Flat washer.



Short bushing

**P/N:** SPACER -15.5 .625"x 10mm x 15.5mm ALUMINUM.



Front right bolt. Bolt 55 with flat washer and lock washer.

STOL CH 701

**Revision 1.0 (1/8/2007)** © 2007 Zenith Aircraft Co

Long bushing

P/N: SPACER-25 .625" x 10mm X 25mm ALUMINUM.

912S RING MOUNT Section 3 - Page 8 of 13



Rear left bolt.


15.5mm spacer fits inside engine mount recessed hole.



**P/N:** Bolt 941-481-55. **P/N:** Lock washer 945-753. **P/N:** Flat washer.



P/N: SPACER 15.5 .625X10mm ALUMINUM.



Long bushing.

P/N: SPACER-25 .625" x 10mm X 25mm ALUMINUM.



Bolt 55 with flat washer and lock washer.

STOL CH 701

Revision 1.0 (1/8/2007) © 2007 Zenith Aircraft Co 912S RING MOUNT Section 3 - Page 9 of 13

		AIRCRAFT ENGINES MAINTENANCE MANUAL II
11.9)	Tightening torqu	
	Adhere to the tighte Catalog (IPC).	ning torques specified. See a
	M4	4Nm (35 in lb)
	M5	
	M6	
	M8	
	M10	
	hex. nut	. housing of sprag clutch
	stud	. cylinder and cylinder head .
	hex. cap nut	. cylinder head
	hex. nut	. cylinder head
	allen screw	. valve cover
	temperature sensor	. cylinder head



**VIBRO STOP P/N:** 316-070.

Nut M6 P/N: 156-014ZP.

**Ref:** Rotax Heavy Maintenance Manual II, section 11.9 page 31. Torque values for Ring Mount attachment bolts.

<image>

Right side view.

STOL CH 701

Revision 1.0 (1/8/2007) © 2007 Zenith Aircraft Co 912S RING MOUNT Section 3 - Page 10 of 13



**ROTAX RADIATOR P/N** 955-697

Screw the rubber dampeners on the radiator (hand tighten).





P/N: 156-014ZP S.L nut

Front view.





Front view of radiator on brackets.



Revision 1.0 (1/8/2007) © 2007 Zenith Aircraft Co

912S RING MOUNT Section 3 - Page 11 of 13





Supplied radiator hose

**P/N:** 71322

Left side view.



Lay the end of the hose even with the edge of the workbench.





Cut to 310mm long. Other half of the hose is not used.

